

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2017

Submitted Date:

12/19/2017

Document Number:

674200367**FIELD INSPECTION FORM**
 Loc ID 452217 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452260	WELL	XX	09/21/2017		123-45494	YELLOWHAMMER 4C-8HZ	DG
452261	WELL	XX	09/21/2017		123-45495	YELLOWHAMMER 13N-17HZ	DG
452263	WELL	XX	09/21/2017		123-45497	YELLOWHAMMER 30N2-8HZ	DG
452266	WELL	XX	09/21/2017		123-45500	YELLOWHAMMER 30N-8HZ	DG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Approx 32' sound walls around location for sound mitigation		
Corrective Action:		Date:	

Equipment:			corrective date
Type:		#	
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type	Field Flare		
Comment:	Not in use at time of inspection		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 452260 Type: WELL API Number: 123-45494 Status: XX Insp. Status: DG

Facility ID: 452261 Type: WELL API Number: 123-45495 Status: XX Insp. Status: DG

Complaint

Comment: Well Number#: Location #: 452217

Inspection Document #: 674200367

Complaint #s: 200444792

Nature of complaint: Odors/Noise

Field Inspector Actions:

On 12-18-2017, I was contacted by complaint specialist Megan Adamczyk in reference to a complaint received for noise on 12-17-2017 by the COGCC about odors occurring in the Erie area west of the Anadarko, Papa Jo location.

I contacted the complainant who indicated he had a strong odor at his residence which he believed was coming from the Anadarko drilling location which was located to the east of his home. The complaint questioned if Anadarko was utilizing a mud chiller on location.

On 12-19-2017 at approx 0730 hrs I performed a complete site inspection of the Papa Jo location and the neighborhoods around the location. At the time of inspection, I observed the Extreme Rig 24 drilling rig performing normal drilling operation on location. I contacted Sean from Anadarko who indicated the rig had been performing normal drilling activity at the time of the complaint. At the time of the inspection of the drilling rig Sean indicated Anadarko was continuing to use an odor neutralizer to mitigate odors at the drilling rig at the time of the complaint. At the time of the inspection all lighting on location appeared to be pointed toward the ground and center of location. I reviewed location records, which did not show any abnormal drilling operations at the time of the complaints.

I also performed a site inspection of the precision rig conducting drilling operations to the east of the Extreme rig at the Papa Jo location east.

As part of the inspection prior to the rig inspection I checked the area of the complaints residence for odors and at the time of the inspection I did not detect any odors off location during my investigation.

All information reviewed and site inspection information were submitted to the COGCC for further review.

No violations of COGCC rules were observed at the time of the inspection

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Extreme 24 Pusher/Rig Manager: Sean Gidding

Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass Test Pressure PSI: Safety Plan: YES

Drill Fluids Management:

Lined Pit: Unlined Pit: Closed Loop: YES Semi-Closed Loop:

Multi-Well: YES Disposal Location: Waste connection

Comment:

Corrective Action:

Date:

Facility ID: 452263 Type: WELL API Number: 123-45497 Status: XX Insp. Status: DG

Facility ID:	452266	Type:	WELL	API Number:	123-45500	Status:	XX	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass			Vehicle Tracking	Pass	
Gravel	Pass	Gravel	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT