

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2017

Submitted Date:

12/21/2017

Document Number:

689700796

**FIELD INSPECTION FORM**

Loc ID 335160 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 211107      | WELL | PR     | 11/07/1994  | GW         | 045-06866 | CLOUGH RMV 4-16   | PR          |
| 279769      | WELL | PR     | 04/27/2007  | GW         | 045-11084 | CLOUGH RWF 343-16 | PR          |
| 279896      | WELL | PR     | 04/27/2007  | GW         | 045-11095 | CLOUGH RWF 433-16 | PR          |
| 279897      | WELL | PR     | 04/27/2007  | GW         | 045-11096 | CLOUGH RMV 164-16 | PR          |
| 279899      | WELL | PR     | 04/27/2007  | GW         | 045-11097 | CLOUGH RWF 431-21 | PR          |
| 279901      | WELL | PR     | 04/27/2007  | GW         | 045-11098 | CLOUGH RWF 534-16 | PR          |
| 279903      | WELL | PR     | 07/31/2008  | GW         | 045-11099 | CLOUGH RWF 33-16  | PR          |
| 279904      | WELL | PR     | 04/27/2007  | GW         | 045-11100 | CLOUGH RMV 151-21 | PR          |
| 279907      | WELL | PR     | 04/27/2007  | GW         | 045-11101 | CLOUGH RWF 434-16 | PR          |
| 279908      | WELL | PR     | 08/18/2008  | GW         | 045-11103 | CLOUGH RWF 541-21 | PR          |
| 279909      | WELL | PR     | 07/31/2008  | GW         | 045-11102 | CLOUGH RWF 334-16 | PR          |
| 279910      | WELL | PR     | 04/27/2007  | GW         | 045-11104 | CLOUGH RWF 333-16 | PR          |
| 279911      | WELL | PR     | 04/27/2007  | GW         | 045-11105 | CLOUGH RWF 344-16 | PR          |
| 279912      | WELL | PR     | 04/27/2007  | GW         | 045-11106 | CLOUGH RWF 543-16 | PR          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                                   |      |       |                 |
|-----------------------------------|------|-------|-----------------|
| Type: Plunger Lift                | # 14 |       | corrective date |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Bird Protectors             | # 8  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Horizontal Heated Separator | # 14 |       |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 2 | 200 BBLS | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 2 | 400 BBLS | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

| <b>Berms</b>       |          |                     |                     |             |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
| Earth              | Adequate | Walls Sufficent     | Base Sufficient     | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

| <b>Venting:</b>    |     |  |  |       |  |
|--------------------|-----|--|--|-------|--|
| Yes/No             | YES |  |  |       |  |
| Comment:           |     |  |  |       |  |
| Corrective Action: |     |  |  | Date: |  |

| <b>Flaring:</b>    |  |  |  |       |  |
|--------------------|--|--|--|-------|--|
| Type               |  |  |  |       |  |
| Comment:           |  |  |  |       |  |
| Corrective Action: |  |  |  | Date: |  |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 211107         | Type: | WELL | API Number: | 045-06866 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279769         | Type: | WELL | API Number: | 045-11084 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279896         | Type: | WELL | API Number: | 045-11095 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279897         | Type: | WELL | API Number: | 045-11096 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279899         | Type: | WELL | API Number: | 045-11097 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279901         | Type: | WELL | API Number: | 045-11098 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279903         | Type: | WELL | API Number: | 045-11099 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 279904         | Type: | WELL | API Number: | 045-11100 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |

|                       |                |                       |            |                  |
|-----------------------|----------------|-----------------------|------------|------------------|
| Facility ID: 279907   | Type: WELL     | API Number: 045-11101 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |                |                       |            |                  |
| Comment:              | Producing well |                       |            |                  |
| Corrective Action:    |                |                       | Date:      |                  |
| Facility ID: 279908   | Type: WELL     | API Number: 045-11103 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |                |                       |            |                  |
| Comment:              | Producing well |                       |            |                  |
| Corrective Action:    |                |                       | Date:      |                  |
| Facility ID: 279909   | Type: WELL     | API Number: 045-11102 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |                |                       |            |                  |
| Comment:              | Producing well |                       |            |                  |
| Corrective Action:    |                |                       | Date:      |                  |
| Facility ID: 279910   | Type: WELL     | API Number: 045-11104 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |                |                       |            |                  |
| Comment:              | Producing well |                       |            |                  |
| Corrective Action:    |                |                       | Date:      |                  |
| Facility ID: 279911   | Type: WELL     | API Number: 045-11105 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |                |                       |            |                  |
| Comment:              | Producing well |                       |            |                  |
| Corrective Action:    |                |                       | Date:      |                  |
| Facility ID: 279912   | Type: WELL     | API Number: 045-11106 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |                |                       |            |                  |
| Comment:              | Producing well |                       |            |                  |
| Corrective Action:    |                |                       | Date:      |                  |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 689700797    | RMV 4-16 photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4333831">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4333831</a> |