

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2017

Submitted Date:

12/22/2017

Document Number:

678301354

FIELD INSPECTION FORM

Loc ID 329282 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249301	WELL	PR	03/05/2010	OW	123-17103	RUMSEY 35-15	EI
447661	TANK BATTERY	AC	09/09/2016		-	RUMSEY-65N66W 35SWSE	EI

General Comment:

[follow-up inspection to 67830128 related to unused equipment. Other parts of inspection as in inspection of 11/22/2017](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: [removed as described in FIRR 401489674](#)

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 249301 Type: WELL API Number: 123-17103 Status: PR Insp. Status: EI

Facility ID: 447661 Type: TANK API Number: - Status: AC Insp. Status: EI