

Photo#1:

View over Cellars with Conductors Set, to Southeast.



December 21, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus N Parachute K10 Loc#335676

Photo#2:

View over Cellars with Conductors Set, to Northwest. Arrows indicate Pipe sections (cut from Conductors, or Rat Holes?) set along outside of each row of Cellars.



December 21, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus N Parachute K10 Loc#335676

Photo#3:

Views of uncovered Cellars with Conductors Set.

Photo#4:



December 21, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus N Parachute K10 Loc#335676



Photo#5:

Photo#6:

Views of BMPs Installed & Repaired.



December 21, 2017