

Inspection Photos  
Location Name: Par-State #28-1  
API: 05-005-06431  
Inspection Date: December 20, 2017



Photo #1 – Well sign.



Photo #2 – Improved conditions at prime mover.

**Inspection Photos**  
**Location Name: Par-State #28-1**  
**API: 05-005-06431**  
**Inspection Date: December 20, 2017**



**Photo #3 – Day tank with secondary containment.**



**Photo #4 – Improved conditions at wellhead.**

## Inspection Photos

Location Name: Par-State #28-1

API: 05-005-06431

Inspection Date: December 20, 2017



Photo #5 – Battery sign.



Photo #6 – Shallow berm at NE corner of battery.



## Inspection Photos


Location Name: Par-State #28-1

API: 05-005-06431

Inspection Date: December 20, 2017



**Photo #7 – Damaged fence on north side of battery.**



**Photo #8 – Oily rag at tank battery.**



## Inspection Photos

Location Name: Par-State #28-1

API: 05-005-06431

Inspection Date: December 20, 2017



**Photo #9 – Improved conditions on north side of produced water AST.**



**Photo #10 – Separator.**

