

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2017

Submitted Date:

12/27/2017

Document Number:

681700970

**FIELD INSPECTION FORM**

Loc ID 413721 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #210  
City: AURORA State: CO Zip: 80016

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J. B.	(303) 680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	<a href="#">All Inspections</a>
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412570	WELL	PR	05/31/2012	OW	005-07144	Par State 28-14 2	EI

**General Comment:**

[COGCC Environmental Inspection. Follow-up to Field Inspection Report \(FIR\) #681700865. For conditions of equipment at shared tank battery, see FIR #681700969.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Prime Mover	# 1		corrective date
Comment:	Oily waste beneath prime mover had been removed by operator in response to previous FIR but has started to accumulate again with continued operations. See photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (prime mover).		Date: <u>01/27/2018</u>

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 412570 Type: WELL API Number: 005-07144 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700974	well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335297">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335297</a>
681700975	wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335298">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335298</a>
681700976	prime mover (1)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335299">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335299</a>
681700977	prime mover (2)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335300">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335300</a>