

Inspection Photos

Location Name: Jean Ann 25-22

API #: 05-123-22929

Location ID: 305408



Wellhead looking east



Stained soil under drain valve on south crude oil tank has been cleaned up