

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326980



Photo 1: Photo taken from the west of the location, facing southeast. Photo shows equipment on site suggesting operator is preparing for reclamation activities.



Photo 2: Photo taken from the west of the location, facing east. Photo shows equipment on site suggesting operator is preparing for reclamation activities.



Photo 3: Photo taken from the north end of the location, facing north. Previous inspection required operator to remove pipe equipment from the location. Photo shows equipment remains.