

Inspection Photos

12/21/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327002

Inspection Doc. Number: 682503010

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327002



Photo 1: Photo taken from the west end of the location, facing west. Photo shows a patch of Canada thistle. Previous inspection documented thistle and had required it's management and removal. Canada thistle is a listed noxious weed and is required to be managed by the COGCC, Colorado State and Weld County. Photo shows thistle does not appear to have been managed or removed per corrective actions.



Photo 2: Photo of Canada thistle stalk remaining on location. Photo shows plants were not managed and appear to have seeded-out. Operator has failed to manage weeds in a timely manner. Canada thistle was not removed per corrective actions in 2017 and was allowed to reach maturity and seed-out. Canada thistle has possibly spread throughout location and adjacent lands.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327002



Photo 3: Photo taken from the south end of the location, facing east. Photo shows pipe riser remaining on location.



Photo 4: Photo taken from the south end of the location, facing southwest. Photo shows pipe riser and trash debris (barrel scraper, can be considered unused equipment) remaining on the location.