



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Clay Elkins (celkins@gobrainstorm.net)  
Submission Date: Dec 21, 2017 10:35:26 AM MST  
Server Receive Date: Dec 21, 2017 10:35:46 AM MST  
Reference Number: 20171221-1870945476  
Location: 15731 N 1st St, Bloomfield, NM 87413, United States  
Dec 21, 2017 10:35:19 AM MST [ [View Map](#) ]

## Information

Name celkins@gobrainstorm.net  
Date Dec 13, 2017  
Well Name REA GAS UNIT 18U-03 3  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Compliance Inspection Actions  
Clean Up Contaminated Soils

## Picture North to South



## Picture South to North



## Picture East to West



Picture West to East



Additional photos

