



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Dec 21, 2017 10:39:33 AM MST
Server Receive Date:	Dec 21, 2017 11:47:54 AM MST
Reference Number:	20171221-1870945565
Location:	3601 N 1st St, Bloomfield, NM 87413, United States Dec 21, 2017 10:38:35 AM MST [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Dec 14, 2017
Well Name	DULIN, ROBERT GAS UNIT B 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

