



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Dec 30, 2017 8:20:24 PM MST
Server Receive Date:	Dec 30, 2017 8:20:33 PM MST
Reference Number:	20171231-1871245279
Location:	4 Road 3336, Aztec, NM 87410, United States
	Dec 30, 2017 8:20:21 PM MST [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Dec 29, 2017
Well Name	MAGOON GAS UNIT C 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Repaired Berm

## Picture North to South



## Picture South to North



## Picture East to West

