



**Photo 1. View of the project area from the southern edge facing northwestward.**



**Photo 2. View of the eastern portion of the project area from the southern edge facing northeastward.**



**Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward. Area is weedy.**



**Photo 4. View of the southeastern portion of the project area from the southeastern corner facing eastward. Revegetation is largely comprised of smooth brome (*Bromus inermis*) and weeds such as cheatgrass (*Bromus tectorum*).**





**Photo 4. View of musk thistles (*Carduus nutans*) in the eastern portion of the project area.**



**Photo 4. View of musk thistles (*Carduus nutans*) in the western portion of the project area and along fenceline of fenced area adjacent to west edge of the well pad.**