

Inspection Photos

Location Name: Bunn I 35-25

API #: 05-123-23193

Location ID: 305581



Wellhead looking south. Wellhead sign has been updated with correct operator information/emergency contact number



Battery looking south. Trash at entrance of location has been removed



Inspection Photos
Location Name: Bunn I 35-25
API #: 05-123-23193
Location ID: 305581



Weeds along west edge of location have been controlled