

SGU CP11D-34 M34
Api# 05-045-14534
Inspection # 689700822



West side of location taken from south.

SGU CP11D-34 M34
Api# 05-045-14534
Inspection # 689700822



East side of location taken from south.

SGU CP11D-34 M34
Api# 05-045-14534
Inspection # 689700822



Unused equipment and 2" riser unmarked, no plug, valve, and no lock out tag out.

SGU CP11D-34 M34
Api# 05-045-14534
Inspection # 689700822



2" riser unmarked, no plug, valve, and no lock out tag out.