

Inspection Photos

Location Name: HSR-West Farms 63N67W #14 NWNW
Location Number: 332625
API: 05-123-19744




Photo 1 Wellhead API 05-123-19744



Photo 2 Pig station for cross country pipeline south of battery



Photo 3 Emission control burner

Inspection Photos

Location Name: HSR-West Farms 63N67W #14 NWNW
Location Number: 332625
API: 05-123-19744



Photo 4 Separators and gas meter runs



Photo 5 Tank Battery