

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2018

Submitted Date:

01/03/2018

Document Number:

679903664

FIELD INSPECTION FORM

Loc ID 321660 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 51065
Name of Operator: LOEB LLC* HERMAN L
Address: P O BOX 838
City: LAWRENCEVILLE State: IL Zip: 62439

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pelton, Shane	620-617-5870	shane@loeboil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207708	WELL	PR	06/26/1998	OW	017-06643	WHITE 'AG' 2	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Bethlehem unit		
Corrective Action:			Date:
Venting:			
Yes/No	YES		
Comment:	1" Casing vent		
Corrective Action:			Date:
Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 207708 Type: WELL API Number: 017-06643 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(White AG-1, AG-2\) 2200' SW @ 38.813120/-102.068630](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT