

# Interim Reclamation and Stormwater Inspection

January 3, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 453032

Weld County, CO

SESW Section 23 T8N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Pierce DE /26-054  
Location ID: 453032



**Photo 1.** Photo taken from the entrance of location off CR90, facing West. Operator has installed a culvert along the bar ditch. Operator has installed gravel but may not be a sufficient tracking pad device by itself.



**Photo 2.** Photo taken from the cut slope of the northern location, facing West. Operator has failed to install stormwater BMPs per Rule 1002.f.(2).

Inspection Photos  
Location Name: Pierce DE /26-054  
Location ID: 453032



**Photo 3.** Photo taken from the western location, facing South. See comments under Photo 2.



**Photo 4.** Photo taken from the southern location, facing East. See comments under Photo 2.



Inspection Photos  
Location Name: Pierce DE /26-054  
Location ID: 453032



**Photo 5.** Photo taken from the eastern location, facing North. See comments under Photo 2. Topsoil stockpile stored along the eastern perimeter and appears to be temporarily stabilized with equipment tracking. Operator needs to stabilize topsoil stockpile for long-term stabilization.