

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2017

Submitted Date:

01/03/2018

Document Number:

680102536

FIELD INSPECTION FORM

Loc ID 335963 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		lrider@caerusoilandgas.com	
		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296840	WELL	AL	10/13/2011	LO	045-16160	N. PARACHUTE EF07D-29 F29 59	RI
296841	WELL	AL	10/13/2011	LO	045-16161	N. PARACHUTE EF03B-32 F29 59	RI
296842	WELL	AL	10/13/2011	LO	045-16162	N. PARACHUTE EF15A-29 F29 59	RI
296843	WELL	AL	02/04/2013	LO	045-16163	N. PARACHUTE EF15B-29 F29 59	RI
296844	WELL	AL	10/13/2011	LO	045-16164	N. PARACHUTE EF12C-29 F29 59	RI
296845	WELL	AL	10/13/2011	LO	045-16165	N. PARACHUTE EF12A-29 F29 59	RI
296846	WELL	AL	10/13/2011	LO	045-16166	N. PARACHUTE EF10B-29 F29 59	RI
296847	WELL	AL	10/13/2011	LO	045-16167	N. PARACHUTE EF11B-29 F29 59	RI
296848	WELL	AL	10/13/2011	LO	045-16168	N. PARACHUTE EF11D-29 F29 59	RI
296849	WELL	AL	10/13/2011	LO	045-16169	N. PARACHUTE EF11A-29 F29 59	RI
296850	WELL	AL	10/13/2011	LO	045-16170	N. PARACHUTE EF14A-29 F29 59	RI
296851	WELL	AL	10/13/2011	LO	045-16171	N. PARACHUTE EF14B-29 F29 59	RI
296852	WELL	AL	10/13/2011	LO	045-16172	N. PARACHUTE EF14C-29 F29 59	RI
296853	WELL	AL	10/13/2011	LO	045-16173	N. PARACHUTE EF03A-32 F29 59	RI
296854	WELL	AL	10/13/2011	LO	045-16174	N. PARACHUTE EF02A-32 F29 59	RI

296855	WELL	AL	10/13/2011	LO	045-16175	N. PARACHUTE EF03C-32 F29 59	RI
--------	------	----	------------	----	-----------	---------------------------------	----

General Comment:

This is an Abandoned Location Inspection, for Sixteen Wells, listed in Related Facilities, above, a Followup to Insp Doc#663902583 Dated 12/31/13. APDs were Approved in 2008 & Abandoned in 2011. The Location was constructed; Wells were not Drilled. Reclamation issues from Previous Inspection have not been Resolved; Site remains, Not Recalimed.

Inspected Facilities

Facility ID: <u>296840</u>	Type: <u>WELL</u>	API Number: <u>045-16160</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296841</u>	Type: <u>WELL</u>	API Number: <u>045-16161</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296842</u>	Type: <u>WELL</u>	API Number: <u>045-16162</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296843</u>	Type: <u>WELL</u>	API Number: <u>045-16163</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296844</u>	Type: <u>WELL</u>	API Number: <u>045-16164</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296845</u>	Type: <u>WELL</u>	API Number: <u>045-16165</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296846</u>	Type: <u>WELL</u>	API Number: <u>045-16166</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296847</u>	Type: <u>WELL</u>	API Number: <u>045-16167</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296848</u>	Type: <u>WELL</u>	API Number: <u>045-16168</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296849</u>	Type: <u>WELL</u>	API Number: <u>045-16169</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296850</u>	Type: <u>WELL</u>	API Number: <u>045-16170</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296851</u>	Type: <u>WELL</u>	API Number: <u>045-16171</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296852</u>	Type: <u>WELL</u>	API Number: <u>045-16172</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296853</u>	Type: <u>WELL</u>	API Number: <u>045-16173</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296854</u>	Type: <u>WELL</u>	API Number: <u>045-16174</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>296855</u>	Type: <u>WELL</u>	API Number: <u>045-16175</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** No disturbance /Location never built **Fail**

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: AL Wells cannot be released for Final Reclamation as Location was built and has Not been Reclaimed. Form4, Dated 5/19/15, Doc#400841276 was filed, Reporting Site was being used as Lay down Yard & inventory of equipment Stored; this does not resolve the status of the Failing Final Reclamation Inspections.

Corrective Action:

Date **06/01/2018**

Reclaim Location. Perform Final Reclamation per COGCC 1004 Rules. Reclamation Activities to be complete by June 1, 2018. Refer to Photos attached for detail of Site Conditions.

Overall Final Reclamation

Fail

Well Release on Active Location

Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102545	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4340063