

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2018

Submitted Date:

01/03/2018

Document Number:

681902458**FIELD INSPECTION FORM**Loc ID 336421 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name      | Phone        | Email         | Comment        |
|-------------------|--------------|---------------|----------------|
| LARA-MESA, SUSANA | 303-825-4822 | cogcc@kpk.com | VP OF ENGINEER |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 241485      | WELL | SI     | 10/01/2017  | OW         | 123-09274 | EARL ANDERSON 2 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | WELLHEAD  |       |            |
| Comment:             | SATISFACTORY  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY   |       |            |
| Comment:             | All wells flowing to this battery are not identified on Battery Sign. |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.b.                               | Date: | 02/02/2018 |
| Type                 | TANK LABELS/PLACARDS  |       |            |
| Comment:             | SATISFACTORY  |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |            |       |  |
|--------------------|------------|-------|--|
| <b>Fencing/:</b>   |            |       |  |
| Type               | PUMP JACK  |       |  |
| Comment:           | Rod fence. |       |  |
| Corrective Action: |            | Date: |  |

|                                   |              |       |                 |
|-----------------------------------|--------------|-------|-----------------|
| <b>Equipment:</b>                 |              |       | corrective date |
| Type: Gas Meter Run               | # 1          |       |                 |
| Comment:                          | SATISFACTORY |       |                 |
| Corrective Action:                |              | Date: |                 |
| Type: Plunger Lift                | # 1          |       |                 |
| Comment:                          | SATISFACTORY |       |                 |
| Corrective Action:                |              | Date: |                 |
| Type: Horizontal Heated Separator | # 1          |       |                 |
| Comment:                          | SATISFACTORY |       |                 |
| Corrective Action:                |              | Date: |                 |
| Type: Bird Protectors             | # 1          |       |                 |
| Comment:                          | SATISFACTORY |       |                 |
| Corrective Action:                |              | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |                       |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 40.122397,-104.992063 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

|                    |   |            |                |         |                       |       |
|--------------------|---|------------|----------------|---------|-----------------------|-------|
| Contents           | # | Capacity   | Type           | Tank ID | SE GPS                |       |
| PRODUCED WATER     | 1 | <100 BBLs  | PBV FIBERGLASS |         | 40.122602,-104.992865 |       |
| Comment:           |   | Longitude: |                |         |                       |       |
| Corrective Action: |   |            |                |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 241485 Type: WELL API Number: 123-09274 Status: SI Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Comment: BRADENHEAD IS NOT PLUMED TO SURFACE FOR PRESSURE MONITORING.Corrective Action: PLUMB BRADENHEAD TO SURFACE.Date: 02/02/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 681902459    | Well and Location | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4340068">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4340068</a> |