

Savage 8-11A  
Api# 05-045-14604  
Inspection # 689700829



Location photo from north view.

Savage 8-11A  
Api# 05-045-14604  
Inspection # 689700829



Separators from east view.

Savage 8-11A  
Api# 05-045-14604  
Inspection # 689700829



**Tank battery form west view.**

Savage 8-11A  
Api# 05-045-14604  
Inspection # 689700829



**Gaps and falling over fence panels.**

Savage 8-11A  
Api# 05-045-14604  
Inspection # 689700829



**Gaps and falling over fence panels.**