

Inspection Photos
Location Name: Kori J 19-10
API #: 05-123-17994
Location ID: 329886



Wellhead looking south. Weeds have been controlled

Previous inspection photo of weeds around wellhead

