

Inspection Photos
Location Name: JSR 4-1
API: 05-081-07070



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: JSR 4-1
API: 05-081-07070



Photo 2. Previous operator and contact information on only sign on location.



Photo 3. Noxious weeds on location. Riser not LOTO at wellhead.

Inspection Photos
Location Name: JSR 4-1
API: 05-081-07070



Photo 4. Noxious weeds on location. Risers not LOTO at meter run. Debris at meter run.



Photo 5. Locked access gate with overgrown road in background.