

Final Reclamation Inspection

January 3, 2018

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-34670

Weld County, CO

SESW Section 20 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BRENT 20-8-66 #1H
API: 05-123-34670



Photo 1. Photo taken from the approximate center of the location, facing North on October 8, 2017. Cheatgrass (*Bromus tectorum*) was the dominant vegetative cover, including, but not limited to, Crested wheatgrass (*Agropyron cristatum*) and Western wheatgrass (*Pascopyrum smithii*).



Photo 2. Photo taken from the same location as Photo 1, facing North on January 3, 2018. Location was brush-hogged and reseeded.

Inspection Photos

Location Name: BRENT 20-8-66 #1H

API: 05-123-34670



Photo 3. Photo taken from the approximate center of the location, facing South on October 8, 2017. See comments under Photo 1.



Photo 4. Photo taken from the approximate location as Photo 3, facing South on January 3, 2018. See comments under Photo 2.