

Final Reclamation Inspection

January 3, 2018

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-34079

Weld County, CO

SWSE Section 2 T9N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: HUTCHISON 2-9-67 #1H

API: 05-123-34079



Photo 1. Photo taken from a portion of the access road, facing South on October 4, 2017. Russian thistle growing throughout the access road portions of the road, gravel still on access road, and access road has not been contoured or seeded.



Photo 2. Photo taken from the approximate location as Photo 1, facing South on January 3, 2018. Operator has removed the Russian thistle from the access road.

Inspection Photos

Location Name: HUTCHISON 2-9-67 #1H

API: 05-123-34079



Photo 3. Photo taken from the entrance of the location, facing South on October 4, 2017. See comments under Photo 1.



Photo 4. Photo taken from the approximate location as Photo 1, facing South on January 3, 2018. See comments under Photo 2.