

Photo#1:
View Southwest over Location Center.



December 20, 2017

Photo#2:
View Southeast over Location Center.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Gasaway API#045-06422

Photo#3:

Debris referenced in 2009 Inspection is still stored at East side of Location.



Photo#4:



December 20, 2017

Inspection Photos: Encana PA Gasaway API#045-06422

Photo#5:

Debris referenced in 2009 Inspection is still stored at East side of Location.

Photo#:



December 20, 2017

Inspection Photos: Encana PA Gasaway API#045-06422