

Photo#1:

View East down Un-Reclaimed Access Road into Location.



December 21, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana ALs N Parachute Loc#335851

Photo#2:  
View North over Reclaimed area of Location.



December 21, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana ALs N Parachute Loc#335851

Photo#3:

View West of Un-Reclaimed Turn around area & Access Road leading out of Location



December 21, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Encana ALs N Parachute Loc#335851