

Photo#1:

There is no Evidence of the XX Well on this Active Location; Conductor has been Closed; Permit has not been Abandoned.



December 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus XX N Parachute API#045-20613