

Inspection Photos  
Location Name: Spring Gulch 1-22  
API: 05-081-06547



**Photo 1. Overview of location taken at entrance facing northwest.**



**Photo 2. Stained soil at loadout and incomplete tank label.**