

Inspection Photos
Location : Cub Creek Vail Pad 1/9/2018
Facility ID # 443507



Photo 1. Ratholes Closed



Photo 2. Ratholes closed



Inspection Photos
Location : Cub Creek Vail Pad 1/9/2018
Facility ID # 443507



Photo 3. Vail 1 Leaks repaired and cleaned



Photo 4. Remediation area pushed up into pile

Inspection Photos
Location : Cub Creek Vail Pad 1/9/2018
Facility ID # 443507



Photo 5. Remediation area looking north



Photo 6. Trash removed

Inspection Photos
Location : Cub Creek Vail Pad 1/9/2018
Facility ID # 443507



Photo 7. Fire extinguisher no tags



Photo 8. Knockout trailer cleaned. Fire extinguisher no tags

Inspection Photos
Location : Cub Creek Vail Pad 1/9/2018
Facility ID # 443507



Photo 9. Chemical tote labeled