

Inspection Photos

Location Name: Great Western 26-13

API #: 05-123-24051

Location ID: 306144



Wellhead looking north. Well is TA



Unused equipment around wellhead needs picked up



Inspection Photos

Location Name: Great Western 26-13

API #: 05-123-24051

Location ID: 306144



Stained soil around wellhead needs cleaned up

