

Final Reclamation Inspection

January 8, 2018

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06159

Inspection Document #: 682403184

Larimer County, CO

SWNW Section 31 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PROCTOR-SKAER #1-A
API: 05-069-06159



Photo 1. Photo taken on January 8, 2018 from the well location, facing North. Operator is IN-PROCESS of reclamation activities regarding the previous corrective action inspection. A follow-up inspection will occur at a future date to ensure compliance with Rule 1004 standards.



Photo 2. Photo taken on January 8, 2018 from a portion of the access road, facing West. Based off aerial imagery, it appears this road is used for ditch access.