

Final Reclamation Inspection

January 8, 2018

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06112

Inspection Document #: 682403187

Larimer County, CO

SESE Section 29 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Google Earth aerial imagery taken June 19, 2014 illustrating an approximate 770' access road AND well location that has not been reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Photo 1. Photo taken on December 12, 2017 from the access point off CO Rd. 16, facing North. Land has been recently tilled. It appears the access road may not have been recontoured as soil material appeared to be elevated along the access road in relation to the adjacent land.



Photo 2. Photo taken on January 8, 2018 from the access point off CO Rd. 16, facing North. Land has been recently tilled and it appears the access road has been recontoured. A follow-up inspection will occur at a future date to ensure compliance with Rule 1004 standards.