

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2017

Submitted Date:

01/09/2018

Document Number:

674200381**FIELD INSPECTION FORM**
 Loc ID 452217 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452260	WELL	XX	09/21/2017		123-45494	YELLOWHAMMER 4C-8HZ	DG
452261	WELL	XX	09/21/2017		123-45495	YELLOWHAMMER 13N-17HZ	DG
452263	WELL	XX	09/21/2017		123-45497	YELLOWHAMMER 30N2-8HZ	DG
452266	WELL	XX	09/21/2017		123-45500	YELLOWHAMMER 30N-8HZ	DG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Approx 32' sound walls surround location for noise and lighting mitigation		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare		
Comment:	Candle stick flare not in use at time of inspection		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 452260	Type: WELL	API Number: 123-45494	Status: XX	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Complaint

Comment: Well Number#: Location #: 452217

Inspection Document #: 674200381

Complaint #s: 200444933-20044829

Nature of complaint: Odors

Field Inspector Actions:

On 12-27-2017, I was contacted by complaint specialist Margaret Ash in reference to a complaint received for noise and lighting on 12-27-2017 and 12-26-2017 by the COGCC about odors occurring in the Erie area west of the Anadarko, Papa Jo location. I attempted to contact the complaint but was not able to make contact by phone. On 12-27-2017 at approx 1530 hrs I performed a complete site inspection of the Papa Jo location. At the time of inspection, I observed the Precision 564 drilling rig performing normal drilling operation on location. I contacted Jason Laub from Anadarko who indicated the rig was performing normal drilling operations on 12-26-2017 and 12-27-2017. At the time of the inspection of the drilling rig Jason indicated Anadarko was using odor solution for mitigation of odor on location. At the time of the inspection all lighting on location appeared to be pointed toward the ground and center of location 1 light on the rig was adjusted in an attempt to possibly solve the complaints lighting issue.

All information reviewed and site inspection information were submitted to the COGCC for further review.

No violations of COGCC rules were observed at the time of the inspection

Corrective Action:

Date:

Facility ID: 452261	Type: WELL	API Number: 123-45495	Status: XX	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 452263	Type: WELL	API Number: 123-45497	Status: XX	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 452266	Type: WELL	API Number: 123-45500	Status: XX	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Compaction	Pass			Vehicle Tracking	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT