

Inspection Photos

API: 05-067-09504

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602405

Inspection Date: 1/4/2018



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northern portion of the project area from the northern corner facing westward.



Photo 3. View of the eastern portion of the project area from northern corner facing southward. Revegetation is progressing with intermediate wheatgrass (*Thinopyron intermedium*) and dropseed (*Sporobolus* sp.).



Photo 4. View of Russian knapweed (*Acroptilon repens*) within the northern portion of the project area.



Photo 5. View of musk thistles (*Carduus nutans*) in the western portion of the project area.



Photo 6. View of sign at the entrance to the well pad.