

SG 24-23
Api# 05-045-12251
Inspection # 689700860



Location photo from north west edge of location.

SG 24-23
Api# 05-045-12251
Inspection # 689700860



Separator anchored on west side of unit.



Separator anchored on east side of unit.

SG 24-23
Api# 05-045-12251
Inspection # 689700860



Tanks anchored on west side of berm.



Tanks anchored on east side of berm.