

Inspection Photos
Location Name: Ross-Government-USA 43-
7
API: 05-081-06298



Photo 1. Overview of location taken at northeast perimeter facing southwest.

Inspection Photos
Location Name: Ross-Government-USA 43-
7
API: 05-081-06298



Photo 2. No wildlife protection apparent on exhaust. Tank label peeling off.



Photo 3. No tank labels.

Inspection Photos
Location Name: Ross-Government-USA 43-
7
API: 05-081-06298



Photo 4. Landfarm area.



Photo 5. Pit.