

Inspection Photos
Location Name: Ptasynski 3
API: 05-081-06354



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Pit.

Inspection Photos
Location Name: Ptasynski 3
API: 05-081-06354



Photo 3. Debris at separator.



Photo 4. Unmarked risers with wooden debris.