

Inspection Photos
Location Name: Ptasynski 4
API: 05-081-06353



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Ptasynski 4
API: 05-081-06353



Photo 2. Pit.



Photo 3. No label on tank.