

Inspection Photos
Location Name: Ptasynski 5
API: 05-081-06493



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Ptasynski
API: 05-081-06493



Photo 2. 1 of 2 pits.



Photo 3. 2 of 2 pits.