

# Inspection Photos

01/11/2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP  
- 47120

Location ID: 319201

Inspection Doc. Number: 682503057  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120  
Location ID: 319201



**Photo 1:** Photo taken from the west end of the former tank battery and facilities location, facing east. Location and final designated land use cropland. Photo shows additional reclamation activities have been conducted.



**Photo 2:** Photo taken from the former tank battery and facilities location. Photo shows additional reclamation activities appear to have been conducted, and site stabilized with crimped straw mulch.