

Inspection Photos

01/11/2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 318950

Inspection Doc. Number: 682503059
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 318950



Photo 1: Photo taken from the northeast corner of the former tank battery location, facing south. Photo shows reclamation in-process.



Photo 2: Photo taken from the west end of the former battery location, facing east. Photo shows reclamation of the access road leading to well.

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 318950



Photo 3: Photo taken from the northeast corner of the well location, facing south. Photo shows reclamation in-process.



Photo 4: Photo taken from the northeast corner of the well location, facing west. Photo shows reclamation in-process.



Photo 5: Photo taken from the access road. Previous inspections documented Scotch thistle present on well/battery locations and access road. This is a Colorado State listed noxious weed requiring management. Operator appears to have performed weed management during reclamation. However, thistle rosettes from new growth post reclamation was found along access road. Weed likely present on both well and battery location. On-going weed management and monitoring will need to be conducted.