

Inspection Photos

01/11/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 405904

Inspection Doc. Number: 682503064

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 405904



Photo 1: Photo taken from the south end of the well location, facing north. Photo shows reclamation activities have been conducted at well and access road.



Photo 2: Photo taken from the east end of the battery location, facing south. Previous inspections required operator to removed abandoned riser. Photo shows riser has not been removed.