

Inspection Photos

01/11/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327240

Inspection Doc. Number: 682503066

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327240



Photo 1: Photo taken from the western end of the battery location, facing south. Photo shows riser has not been removed in accordance to 1004.a and corrective actions



Photo 2: Photo taken from the east end of the battery location. Photo shows pipe riser that has been tagged and painted per the 2017 Flowline NTO, but has not been removed per the NTO required dates. This riser will need to be removed per the NTO and 1004.a.