

Inspection Photos

01/11/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327399

Inspection Doc. Number: 682503074

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327399



Photo 1: Photo taken from the northwest end of the well location, facing southeast. Photo shows location remains predominantly undesirable weedy plant species. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.



Photo 2: Photo taken from the well location. Photo shows location remains predominantly undesirable weedy plant species. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.



Photo 3: Photo taken from the adjacent reference area. Photo shows vegetation appears to be predominantly perennial grasses such as sand dropseed.



Photo 4: Photo taken from former battery location. Photo shows meter shed equipment has not been removed per corrective actions.