

Inspection Photos

API: 05-067-09536

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602415

Inspection Date: 1/4/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from northeastern corner facing southward. Revegetation is progressing but is grazed and not in identifiable form at this time. Grazing should be monitored as cattle exclusion may be needed if vegetation doesn't recover.



Photo 4. View of erosional channels in the southeastern portion of the project area.