

Photo#1:

View North from Main Road, over Access Road & into Location.



December 29, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PDC PA Puckett API#045-13353



Photo#2:  
View Northwest over Location from Entry.



December 29, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PDC PA Puckett API#045-13353

Photo#3:

View to East over Position of PA Well indicated by Stake.



December 29, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PDC PA Puckett API#045-13353



Photo#4:

View to Northeast along East Fill Slope.



December 29, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PDC PA Puckett API#045-13353



Photo#5:  
Pad remains Graveled



December 29, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PDC PA Puckett API#045-13353