

Inspection Photos
Location Name: A.P. Urie 2
API: 05-081-05288



Photo 1. Overview of location taken at east entrance facing northwest.



Photo 2. Stained soil at wellhead and chemicals without secondary containment.