

## Inspection Photos

Location Name: [Champlin 248 Amoco #c-5]

API: 05-001-07987



**Well sign**



**Soiled dirt inside pump jack house**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources