

Photo#1:
Overview of Location from Entry to East.



January 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335070

Photo#2:
View Down Fill Slope from Top of Pad at Erosion
Channeling.



Photo3:
View Up from bottom of Fill Slope at Erosion
Channeling.



January 8, 2018

Photo#4:

View over Expanse of Fill Slope to South; Slope roughening / BMPs may be beneficial.



January 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Clough Loc#335070